


GLoucester COUNTY



① OAK GROVE SUBDIVISION
SECTION ONE
P.B. II, Pg.20, LOTS 1-10


② SECTION TWO
P.B.II, Pg.79 LOTS 11-17

③ SECTION TWO
P.B.16, Pg.34, LOTS 18-24

④ TRIPLE G FARMS
P.B.20, Pg.89
LOT 3 REVISED P.B.23-466, 12/1/97

INSERT 23A


WARE



- ① POPLAR SPRINGS
P.B.16, pg.99, LOTS 1-7, 9, 10, 12-14
- ② POPLAR SPRINGS
P.B.20, pg.389, LOTS 8,11, 15-20
- ③ POPLAR SPRINGS-SECTION TWO-
P.B.20, Pgs. 726 & 726A
LOTS 50-87
Revised Lots 70 & 71, P.B.25, Pg.342 4/21/05
- ④ POPLAR SPRINGS
P.B.21, Pg.208
LOTS 21-49 & 88 10/86

INSERT 23B

PETSWORTH



PETSWORTH & WARE DISTRICT

SECTION 23A, 23B
INSERT